Work Order ID 57635

Monday, April 12, 2010 11:44:04 AM



Page 1

Item ID:

D412-702-123B

Accept

Setup Start



Revision ID:

Item Name:

Harness Assembly

Start Date:

4/12/2010

Start Qty: 1.00

Required Date: 4/14/2010 Req'd Qty: 1.00



Cust Item ID: Customer:

Reference:

Approvals:

Process Plan: M

Revision Nbr

Date: 10-4-12 Tooling:

Date: _____ SPC (Y/N):

0.00

Date:

Date:

Run

Start

Stop



Sequence ID/ **Work Center ID** Operation Description Set Up/ **Run Hours**

Draw Number

Draw Plan Rev. Code

Accept Qty

Reject Reject Qty

Insp. Number Stamp

Draw Nbr

DSI 9469 Α

50

Document Control

Memo

0.00

Photocopy bluefile &type labels per PPP D412-702-123B / DSI 9469

CHG001

100

Packaging

Pick Kit

Memo

0.00

0.00

0.00

Packaging

110

Small Fab Small Fab

Memo

0.00

Assemble as per DSI9469

W/O:			147	ODI ODDED OUA	IOFO							
W/O:				ORK ORDER CHAI	NGES							
DATE	STEP	PRO	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
										ļ		
					·							
							7 2					
		PAR #:	Fault Cate	egory:	NCF	NCR: Yes No DQA: Date:						
		solution:										
NCR:		•	WORK ORD	ER NON-CONFOR	MANCE	(NCR)					
DATE	STEP	Description of NC	1-24-1	Section B	0:	Verific	ation	Approval	Approval			
		Section A	Initial Chief Eng	Action Descriptio	on	Sign & Date	Secti	on C	Chief Eng	QC Inspector		
										-		
						,		-				
								į				
		,										

Work Order ID 57635

Monday, April 12, 2010 11:44:04 AM



Page 2

Item ID:

D412-702-123B

Accept

Setup Start

Stop



Revision ID:

Item Name: Harness Assembly

Start Date:

4/12/2010

Start Qty: 1.00

Required Date: 4/14/2010

Req'd Qty: 1.00



Cust Item ID: Customer:

Reference:

				1
A	DD	ro	va	is:

Process Plan:

QC:_____

Date:

Date: Tooling:

SPC (Y/N):

Date:

Date:

Run

Start

Stop

Reject

Qty

: .



Set Up/ **Run Hours**

Draw Number Draw Plan Rev. Code

Accept Qty

Reject Number Stamp

Insp.

Work Center ID 120

Sequence ID/

Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

130



Packaging

Memo

Memo

0.00

0.00

Packaging

Identify and pack for shipping as per PPP D412-702-123B / DSI 9469

Location:

PPP rev:____

140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

W/O:			W	ORK ORDER CHANG	ES						
DATE	STEP	PRO		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
					<u>-</u> -		· - · · · · · · · · · · · · · · · · · · ·	1.			
ı									-		
Part No: PAR		PAR #:	Fault Cat	_ NCI	R: Yes	No DQ	A:	: Date:			
	R	esolution:	Dispositi	on:	_ QA	Date:					
NCR:			WORK ORI	DER NON-CONFORMA	ANCE	(NCR)				
DATE	STEP	Description of NC Section A	Corrective Action Section B				Verific	cation	Approval	Approval	
	0,2,		Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti	on C	Chief Eng	QC Inspector	
										-	
		·	-								
·											

Picklist Print

Monday, April 12, 2010 11:44:04 AM

Work Order ID: 57635

D412-702-123B

Parent Item Name: Harness Assembly

Comments:

Parent Item:



Start Date: 4/12/2010

Required Date: 4/14/2010

Start Qty: 1.00

Required Qty: 1.00

									tart Qty. 1.00		Required Qty.	
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
D3570-4		Manufactured	No				Each	16.0000	1.0000	510,	64/13	
STACKET				<u>Warehoo</u> <u>Loca</u>	tion	Loc	<u>Otv</u>	Loc Code				
				Main Wa ST24	15A	1	16 16			1		
03579-048 	II	Manufactured	No				Each	4.0000	1.0000	5/0	/o4 / a /	·3
nounce Trainess				Warehoo Loca	tion	Loc	<u>Oty</u>	Loc Code			/	
				Main Wa			4					
// // // // // // // // // // // // //		Purchased	No		33063		Each	138.0000	4.0000	15,0	/o4 /13	1 P 14 - 3 4
cicw				<u>Warehoo</u> <u>Loca</u>		Loc	<u>Oty</u>	Loc Code				
				Main Wa ST28			138					

11110									
W/O:			WC	ORK ORDER CHANG	ES			•	
DATE	STEP	PRO	PROCEDURE CHANGE						Approval QC Inspector
			-					Prod Mgr	
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DG	A:	Date: _	
Part No:									
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NC	R)		-	
DATE	STEP	Description of NC		Corrective Action Section		Verifi	ication	Approval	Approval
	Section A		Initial Chief Eng	Action Description Chief Eng	Sign Date	& Sec	tion C	Chief Eng	QC Inspector
				·					-
					·				
				•			. •	-	

Picklist Print

Monday, April 12, 2010 11:44:04 AM

Page 2

Work Order ID: 57635

Parent Item:

D412-702-123B

Parent Item Name: Harness Assembly



Start Date: 4/12/2010

Required Date: 4/14/2010


Comments:								s	tart Qty: 1.00		Required Qty: 1.0	00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
AN960JD10L		Purchased	No				Each	4,609.000	4.0000	5/0/	64/13	
1AS 1149 DO 36	~ 2 ~ ~	237		Warehou Loca Main Wa	tion	<u>Loc (</u>	<u>Otv</u>	Loc Code		,	<i>7.</i>	
1-1116				ST34			4609					
MS21042L3		Purchased	No		110985	2	4609 Each	1,335.000	1.0000	1510	0/04//3	
Nut				<u>Warehou</u> Loca		<u>Loc (</u>	<u>Qty</u>	Loc Code				
				Main Wa			1225					
				ST30	113537 113644	·	1335 351 984		· —	4		
D3569-3		Manufactured	No				Each	5.0000	1.0000	•		
Decal A A	\mathcal{L}			Warehou Loca Main Wa	tion	<u>Loc (</u>	<u>Oty</u>	Loc Code				

ST245A


56385

	•								
W/O:			WC	RK ORDER CHANG	ES				
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
Part No	·	PAR #:	Fault Cate	jory:	NCR: Yes	No DQ	A:	Date: _	
	Re	esolution:	Disposition	:	_ QA: N/C Clo	osed:		Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR)			
DATE	STEP	Description of NC		on B	Verific	cation	Approval	Approval	
	Section A		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Secti	on C	Chief Eng	QC Inspector
									-
	.								
				÷					
							:		

ICA Page 79 (80 blank) of 98



DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND D412-702-101B/-103B/-105B/-107B/-109B/-115B/-117B HARNESS ASSEMBLIES (BELTS, K6.2 CLIP AND D3569-1/-2/-3 DECAL NOT SHOWN)



DETAIL 'L' D412-702-111A/-111B/-113A/-113B HARNESS ASSEMBLIES (BELTS AND D3569-1/-2/-3 DECALS NOT SHOWN)

COPYRIGHT © 2004 BY DART AEROSPACE LTD. •

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

W/O:			WC	RK ORDER CHAN	GES				
DATE	STEP	PRO	OCEDURE CHAI	Ву	Date Q	ty Approval Chief Eng / Prod Mgr	Approval QC Inspector		
			•						
			<i>,</i>						
Part No	:	PAR #:	Fault Cated	lorv:	NCR: Yes	No DOA:	Date	<u> </u>	
					QA: N/C Closed: Date:				
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NCR)		**************************************	
DATE	STEP	Description of NC			ection B	Verification	n Approval	Approval	
	1	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		QC Inspector	
				in the second second				-	
	(
		1:							
				·					